

Schwinn 190 & 290 Bikes: Console displays "5 NVRAM Error" error code

ID: 15877.1

Common issue descriptions:

- Error message or error code
- 5 NVRAM Error
- NVRAM, RAM, or console memory error

Tools used in this guide: - None -

Estimated time to complete: Less than 5 minutes

Let's get started!

Replace the console

1. A "5 NVRAM Error" indicates there is a problem with the flash memory on the console.
2. To resolve the issue, a console replacement is needed - [order a Console \[15877.A\]](#).

Need to order replacement parts?

1 Parts Reference Table

<i>Model & Part Description</i>	<i>Part SKU</i>
Console	8026988

2 Contact Tech Team / Advanced Troubleshooting

If the issue was not resolved in the steps listed, contact the Tech Team or send an Advanced Troubleshooting case.

Submit a Case with case type Advanced Troubleshooting