







TITLE: EXP VIEW DWG- BFX LX5 LATERAL TRAINER			
DRAWN: J.MORGAN	DOC. PART NO.: 100602-W	PRODUCT SKU NO.: 100602	REV.: F
DATE: 09/18/2018			



*** When replacing lateral link ref # 24 also send link puller tool ref # 900**



*** When replacing lateral shrouds ref #s 45, 46, 47, or 48 on an assembled machine also send lateral link puller tool ref# 900 as link must be removed to replace shrouds.**